



The Testcenter facility 'LoRa® Test Lab' within IMST GmbH is recognized by the LoRa® Alliance for testing in accordance to the LoRaWAN® Specification V1.0.2

## Report for Certification by Similarity according to LoRaWAN® V1.0.2

for the Device

## "Abeeway Micro Tracker"

for the Customer

"Actility"

Jens Lerner Yavuz Turan

29<sup>th</sup> March, 2022

## pruefbericht\_eng.doc\01.07.10\V3.2\YT

## **Administrative Summary**

Location: IMST GmbH, Test Centre, Kamp-Lintfort, Germany

Responsible Test Engineer: Yavuz Turan, Jens Lerner

Subject: Test of Conformance to LoRaWAN® Specification V1.0.2

Company and Contact Information:

Actility

Rohit Gupta

65-67 Rue de la victoire

75009 Paris

France

**Checked Device:** Abeeway Micro Tracker

Hardware version: ABW004E1.x

Firmware version: AT 2.x

<u>Type and Version of used Stack:</u> 1.02 tag 4.4.0 Version <u>Original End-device identifier:</u> Abeeway Smart Badge

LoRa Device Class: A

LoRaWAN Specification version: V1.0.2

Certification requirements: LoRa End Device Certification by Similarity V1.1

Frequency band(s): 868 MHz
Type of Certification by Similarity:

Case 3: Certification of an end-device variant from a certified end-device

Variant device differences to the referenced certified device:

- Same LoRa transceiver
- Same LoRaWAN protocol SW version
- Same MCU Core
- Same Clock design and implementation

Brief description of the differences between the primary and the variant device

The main differences are in terms of antenna design, casing and battery type. The industrial tracker does not have LED and buzzer which is present in the smart badge.

Date: 29<sup>th</sup> March, 2022

The Test Report, No. 6220133 has the following conclusion:

The device fulfils the requirements.

Responsibility: / (

Applov

Jens Lerner

Yavuz Turan Test Engineer

**Quality Engineer** 

Copyright Notice & Disclaimer: No part of this test report may be reproduced without written permission of IMST GmbH. The test results herein only refer to the tested sample. IMST GmbH cannot be made responsible for any generalizations or conclusions drawn from the test results presented herein concerning further samples of the tested device. Modification of the tested sample(s) is prohibited and leads to invalidity of this report.

