



The Testcenter facility 'LoRa[®] Test Lab' within IMST GmbH is recognized by the LoRa™ Alliance for testing in accordance to the LoRaWAN™ Specification V1.0.2

Report for Certification by Similarity according to LoRaWAN™ V1.0.2

for the Device

"EcoLoRa"

for the Customer

"1M2M B.V."

Dietmar Krebs Yavuz Turan

17th October, 2019

pruefbericht_eng.doc\01.07.10\V3.2\YT

Administrative Summary

Location: IMST GmbH, Test Centre, Kamp-Lintfort, Germany

Responsible Chief Check Engineer: Dietmar Krebs

Subject: Test of requirements for Certification by Similarity according to LoRaWAN™ Specification

V1.0.2

Company and Contact Information:

1M2M B.V.

Mr. Jean Pierre Hoefnagel

Pastoor Ohllaan 39, 3451 CB Vleuten

The Netherlands

<u>Checked Device:</u> EcoLoRa <u>Firmware version:</u> V1.0 <u>Hardware version:</u> V1.0

Type and Version of used Stack: own Version 1.02

Original End-device identifier: ED1610

LoRa Device Class: A

LoRaWAN Specification version: V1.0.2

Certification requirements: LoRa End Device Certification by Similarity V1.0

<u>Frequency band(s):</u> 868 MHz <u>Type of Certification by Similarity:</u>

Case 3: Certification of an end-device variant from a certified end-device

Variant device differences to the referenced certified device:

- Same LoRa transceiver
- Same LoRa protocol SW version
- Same MCU Core
- Same Clock design and implementation

Brief description of the differences between the primary and the variant device

The internal antenna is no longer mounted but is replaced by a 50 ohms resistor. The external antenna is still an UFL that is connected to a whip antenna on the outside of the enclosure.

Date: 17th October, 2019

The Test Report, No. 6191344 has the following conclusion:

The device fulfils the requirements

Responsibility:

Yavuz Turan

Approved:

ietmar Krebs

Test Engineer

Quality Engineer

Copyright Notice & Disclaimer: No part of this test report may be reproduced without written permission of IMST GmbH. The test results herein only refer to the tested sample. IMST GmbH cannot be made responsible for any generalizations or conclusions drawn from the test results presented herein concerning further samples of the tested device. Modification of the tested sample(s) is prohibited and leads to invalidity of this report.

